Product information No. 658A December 2020



OJ-Air2 Software version 5.24

OJ-Air2 software version 5.24 is released for up-grade with the SD-card. In the production at OJ Electronics version 5.22 is still used, until further notice.

Changes

Compared to version 5.22 there were following improvements:

Functional description

No changes. Functional description OJ-Air2 01 is still valid.

Functionality

 Pre-heater frost protection setpoint min. value changed from +2°C to -30°C (UOE-9046)

Web

No changes

Cloud

No changes

OJ-Air2-HMI-35T

No changes

Hand terminal

No changes.

Alarms

Cooling alarm delays changed back from 10s to 3s. (UOE-9166)
Alarm 80 "Cooling fault"

Alarm 81 "Low cooling pressure circuit 1"

Alarm 82 "High cooling pressure circuit 1"

Alarm 83 "Cooling fault 1: Compressor 1 overheated circuit 1"

Alarm 84 "Cooling fault 2: Compressor 2 overheated circuit 1"

Alarm 85 "Low cooling pressure circuit 2"

Alarm 86 "High cooling pressure circuit 2"

Alarm 87 "Cooling fault 3: Compressor 1 overheated circuit 2"

Alarm 88 "Cooling fault 4: Compressor 2 overheated circuit 2"

Alarm 90 "Pressure sensor fault: DX low pressure 1"

Alarm 91 "Pressure sensor fault: DX high pressure 1"

Alarm 92 "Pressure sensor fault: DX low pressure 2"

Alarm 93 "Pressure sensor fault: DX high pressure 2"

Modbus registers

No changes

BACnet

No changes





Affected articles

OJ-Air2Master.

Coming into force

Version 5.24 is released for up-grade with SD-Card in week 51 2020.

Compatibility

No changes are required when upgrading from version 5.22 to 5.24.

Updating with the SD card

The OJ-Air2Master has to be with **software version 3.01** or higher. The following files must be copied to the SD card:

- "air2_v207_update_rd.gz"
- "version.crc" (1kB, 14-12-2020, 09:31)
- "air2_v524_update_jffs2.tar.gz"

OBS: This update requires three files on the SD-card, since the memory allocation has to be re-arranged in the OJ-Air2Master to software 5.xx layout. Due to the large amount of data, this update has a duration of approximately 8 minutes, if the current software version is lower than 5.01. See details on next page.

WARNING: Do not power off the OJ-Air2Master during the update.

The files are available at OJ Electronics Customer Login: https://ojelectronics.com/support

Up to 8Gb HC SD cards can be used from version 2.19. The SD-card shall have a MBR with msdos partition table, and the first primary partition in it shall be VFAT (or FAT32) file system.

https://ojelectronics.com/support





Software 5.0x update sequence if current software version is lower than 5.01:

WARNING: Do not power off the OJ-Air2Master during the update sequence. It will damage the internal files and the OJ-Air2Master will need service at OJ Electronics factory.

- 1. Copy the **three** files to a SD card (Max. SD-card size is 8Gb)
- 2. Insert the SD card in the OJ-Air2Master
- 3. Wait approximately one minute until the new software is detected
- 4. Press update button in HMI
- 5. Wait 8 minutes until the update sequence has completed DON'T touch anything, just let the process run.


The HMI will show these screens during the update

The first screen

After 4 minutes

After 6 minutes








Flashing after 7 minutes

Update completed after 8 minutes 12:57 PM, Tue





6. Verify the update was successfull



OJ-Air2-HMI-35T SW 1.37 is OK OJ-Air2-Master SW 5.24 is OK

